

N

 Kennecott Barneys Canyon Mining Company 8200 South 9600 West
 P. O. Box 311
 Bingham Canyon, UT 84006-0311 (801) 569-7200
 FAX (801) 569-7190

Dennis M. Kerstiens General Manager

January 07, 1997

D. Wayne Hedberg Permit Supervisor Department of Natural Resources Division of Oil, Gas and Mining 335 West North Temple Salt Lake City, Utah 84180-1203

Dear Mr. Hedberg:

Attached please find the annual report of mining operations as requested in your letter of December 10, 1996.

It includes Mining operations for the Barneys Canyon Mine for 1996.

If you require further information, please call.

Dennis Kerstiens General Manager Barneys Canyon Mine 8200 South 9600 West

P. O. Box 311

Bingham Canyon, Utah 84006-0311

JAN 1 0 1997

DIV. OF OIL, GAS & MINING

Kennecott Minerals

STATE OF UTAH DEPARTMENT OF NATURAL RESOURCES DIVISION OF OIL, GAS AND MINING

1594 West North Temple Suite 1210 PO Box 145801

Salt Lake City, Utah 84114-5801 Telephone: (801) 538-5291 Fax: (801) 359-3940

ANNUAL REPORT OF MINING OPERATIONS

The informational requirements of this form are based on provisions of the Mined Land Reclamation Act, Title 40-8, Utah Code Annotated 1953, as amended, and the General Rules as promulgated under the Utah Minerals Regulatory Program. An operator conducting mining operations under a Notice of Intention must file an annual operations and progress report (FORM MR-AR) with the Division.

| . <u>Gen</u> | veral Information | | |
|--------------|--|--|--|
| 1. | Report Time Period: From (mo./yr.) 1/96 To (mo./yr.) 1/97 | | |
| 2. | DOGM File Number (Mine No): M / 035/009 | | |
| 3. | Mine Name: Barneys Canyon Mine | | |
| 4. | Mineral(s) Mined (or permitted to mine):Gold | | |
| 5. | Type of mine | | |
| 6. | Legal Description (Location of Lands Affected): | | |
| | \underline{SW} 1/4, $\underline{\hspace{1cm}}$ 1/4, Section $\underline{\hspace{1cm}}$ 36, Township $\underline{\hspace{1cm}}$ 25, Range $\underline{\hspace{1cm}}$ 3W | | |
| | <u>SW</u> 1/4,1/4, Section 2 , Township 35 , Range 3W . | | |
| | <u>SE</u> 1/4,1/4, Section <u>3</u> , Township <u>35</u> , Range <u>3W</u> | | |
| 7. | Name of Operator or Company: Barneys Canyon Mining Co. | | |
| 8. | Permanent Street Address: 8200 South 9600 West | | |
| | City, State, Zip: Bingham Canyon, Utah 84006-0311 | | |
| | Phone: (801) 569-7200 | | |
| 9. | Company Representative (or designated operator): | | |
| , | Name: Dennis Kerstiens | | |
| | Title:General Manager | | |
| | Business Address: P. O. Box 311 | | |
| | City, State, Zip:Bingham Canyon, Utah 84006-0311 | | |
| | Phone: (801) 569-7200 | | |
| | Please check if any of the above information has changed since previous year. | | |
| <u>Mini</u> | ing and Reclamation | | |
| 1. | Was the mine active during the past year? Yes ☒ No ☐ | | |
| 2. | If active, how much ore or mineral was mined? 2.4 m Tons | | |

| | 3. | How 1. A additional acreage was disturbed cng the past year? 94 ac | | |
|----------------------|------------|--|--|--|
| , . | 4. | Briefly describe any new or additional surface disturbances that occurred during the past year. This description should include the type of work performed, and volume of material moved. | | |
| | 53 | 3 ac disturbed for Melco north dumps. 5 ac disturbed during reclamation | | |
| | <u>e f</u> | ffort on 6300 dump area. 18 ac disturbed to strip topsoil for Melco | | |
| | <u>nc</u> | orth dump area. | | |
| 5. | H | Now much acreage was reclaimed during the past year? | | |
| 6. | de Th | riefly describe the reclamation work performed during the past year. This escription should include methods employed, and an evaluation of the results. he 6300 dump area (50 ac) was dozed to 2 1/2:1 slope, topsoiled and ill be seeded as weather allows. Dozer work 20% complete for the | | |
| | | 400-6500 Barneys dumps. | | |
| | | 400 0300 Barneys dumps. | | |
| 7. | W | That is the total disturbed acreage at years end?989 ac | | |
| 8. | Br | Briefly summarize any mining and/or reclamation plans for the upcoming year. | | |
| | | emplete dozer work to slope to 2 1/2:1 grade for the 6400 & 6500 | | |
| | | umps, except where reclaimed dump interfaces with haul road. | | |
| | | | | |
| | | | | |
| NOTE: | Sec | ction III., "Additional Information" applies only to large mining operations. | | |
| III. <u>Addition</u> | al In | <u>oformation</u> | | |
| 1. | An maj | updated surface facilities map should be attached if there have been significant changes since the previous p was submitted. | | |
| 2. | An; sho | y monitoring results or other reports that are required under the terms of the approved notice of intention ould also be attached. | | |
| IV. Signature | e Reg | <u>quirement</u> | | |
| I her | eby o | certify that the foregoing is true and correct. | | |
| | Na | me (Typed or Print): Dennis M. Kerstiens | | |
| | Tit | le of Operator: General Manager | | |
| | Sign | nature of Operator: | | |
| | | Date: | | |
| jb MR-AR | | | | |